

ZCZCDPG586

DAN: 467-054705

INPUT CDSN: DKI171

BFN: PA201906

TOR: 202104Z JAN 87

TOT: 202104Z JAN 87

ROUTING= DPG

WIRE SVC= \*\*UNASSIGNED\*\*

COMMDIS=\*\*UNASSIGNED\*\*

RTTUZYUW RUEGFA0127 0201905-UUUU--RUTLAAB.

ZNR UUUUU ZYN ZPO

R 201906Z JAN 87

FM FBIS  PM

STAT

TO RUTLAAB/FBIS WASHINGTON DC

ACCT FBPA-EWDK

BT

UNCLAS

ATTN

STAT

ONLY FSB/FED

SUBJ

SERVICE: INTERNET EQUIPMENT WEEKLY REPORT

PA201906

HAVE NOT EXPERIENCED THE AIR CONDITIONING PROBLEM  
(STICKING RELAY) THAT WAS REPORTED IN PREVIOUS WEEKS BUT  
THE UPS ALARM PROBLEM CONTINUES. HAVE MANAGED TO FIND THE  
SPECIFIC ALARM CONDITION THAT IS CAUSING THE UPS ALARM; IT  
IS BYPASS OVER/UNDER FREQUENCY. HOWEVER, WHEN THE BYPASS  
FREQUENCY IS MONITORED, EVEN DURING THE ALARM, IT IS 60.0  
HZ SO THE PROBLEM IS IN THE ALARM REPORTING SYSTEM AND NOT  
TRUE FAULT. EVERYTHING ELSE IS OK. REGARDS.

20/1908Z JAN

BT

#0127

NNNN